

Technical data sheet

Follow-up safety inspection

Part no.: S991019

CS-SIO/FR

Contents

- Technical data



Figure can vary

Technical data

Basic data

Description	Follow-up safety inspection for a third-party device
Details	Inspection of an ESPE application in accordance with current standards and directives, inspection of the device and machine data, preparation of a test protocol per ESPE application.

Classification

eCl@ss 8.0	40020690
eCl@ss 9.0	40020690